

Updated 07/19/2022

| BDTM No. | Subject | Issue Date | Revision 1 Date | Revision 2 Date | Revision 3 Date | Reason for Archiving |
|---------------------------|---|------------|-----------------|-----------------|-----------------|---|
| Memo 1 | Clarification of LRFD Policy Memo | 1/22/2007 | | | | |
| Memo 2 | DOTD LRFD Implementation | 4/10/2007 | | | | |
| BDTM.01 | Website update and publication of LRFD Bridge Design Manual version 2008.1 | 11/21/2008 | | | | Incorporated into BDEM (various sections) |
| BDTM.02 | Live Load Factor for Service III Limit State | 2/13/2009 | | | | Incorporated into BDEM Table 3.4.1-1 |
| BDTM.03 | Publication of Policies and Guidelines for Bridge Rating and Evaluation | 4/2/2009 | | | | Incorporated into BDEM Pt II Vol 5 |
| BDTM.04 | DOTD Design Standards | 7/27/2009 | | | | Incorporated into BDEM Part II V1 2.3.2.2.3 |
| BDTM.05 | Publish ProjectWise Document Control Procedure | 8/18/2009 | | | | Obsolete - Replaced by "SOP - Document Management Procedures" published under BDTM.101." |
| BDTM.06 | Suspension of Empirical Deck Design | 9/2/2009 | | | | Incorporated into BDEM Pt II Vol 1 - 9.7.2.1 |
| BDTM.08 | Revision of the Policies and Guidelines for Bridge Rating and Evaluation | 9/22/2009 | | | | Incorporated into BDEM Pt II Vol 5 |
| BDTM.09 | Policy on Distribution of Bridge Standard Plans and Special Details | 10/21/2009 | | | | Incorporated into BDEM Pt I - 9.3 |
| BDTM.11 | Use of Preliminary Stamp | 11/23/2009 | | | | Obsolete, stamp has been replaced with new stamps |
| BDTM.14 | Friction Connection Criteria Clarification | 5/3/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 6.13.2.8 |
| BDTM.15 | Vertical Reinforcement in Prestress Girders for Overpass Structures | 5/5/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 5.8.2.7 |
| BDTM.17 | Epoxy Coated Reinforcing Steel | 5/21/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 5.4.3.1 |
| BDTM.19 | Prestressed Girder Deck Cantilever | 9/27/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 9.7.1.5 |
| BDTM.23 | Bridges Vulnerable to Coastal Storms | 11/15/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 1.1 |
| BDTM.24 | Welded Shear Studs | 11/15/2010 | | | | Incorporated into BDEM Pt II Vol 1 - 6.10.10.1 |
| BDTM.25 | Policy on Responsibility for Bridge Standard Plans and Special Details | 11/24/2010 | | | | Incorporated into BDEM Pt I Ch 3 |
| BDTM.26 | Retention Policy for Shop Drawings and Working Drawings | 12/22/2010 | | | | Incorporated into BDEM Pt I Ch 3 Appendix F |
| BDTM.27 | Design Limits and Special Notes for Precast Prestressed Concrete Girders | 2/14/2011 | | | | Incorporated into BDEM Pt II Vol 1 - 5.14.1.2 |
| BDTM.28.1 | Louisiana Design Vehicle Live Load 2011 (LADV-11) | 4/5/2011 | 8/26/2011 | | | Incorporated into BDEM Pt II Vol 1 - 3.6.1.2 |
| BDTM.29 | As-Designed Bridge Rating | 4/5/2011 | | | | Incorporated into BDEM Pt II Vol 5 - 6A.1.1 in Section 6 |
| BDTM.35 | Records Retention Policy | 1/27/2012 | | | | Incorporated into BDEM Pt I Ch 3 Appendix F |
| BDTM.37 | Bridge Design Section Policy On QC/QA | 10/30/2012 | | | | Incorporated into BDEM Pt I Ch 3 |
| BDTM.38 | Publication of EDSM I.1.1.28 - Procedures for Final Plan Modifications | 3/25/2013 | | | | Obsolete, replaced by BDTM.100 |
| BDTM.40.1 | Design Policy for Bridge Rehabilitation-Repair Projects | 7/15/2013 | 2/6/2014 | | | Incorporated into BDEM Pt I Ch 6 |
| BDTM.41 | Pre-Approved Software List | 7/15/2013 | | | | Incorporated into BDEM Pt I - 3.5 |
| BDTM.42 | Publication of Steel Panel Detour Bridge Special Details | 7/23/2013 | | | | These details are no longer available for use |
| BDTM.43 | Expiration Date for Task Orders and Consultant Contracts | 8/15/2013 | | | | Obsolete. See Consultant Contract Services for guidance |
| BDTM.46 | Concrete Cover in Roadway Median Barriers | 2/6/2014 | | | | Incorporated into BDEM Pt II Vol 1 - 5.12.3 |
| BDTM.51 | Publication of Updated Special Details - High-Mast Lighting | 12/2/2014 | | | | Obsolete, replaced by BDTM.58 |
| BDTM.54.1 | Patented and Proprietary Products | 3/3/2015 | 6/18/2015 | | | 23 CFR rescinded on 09/27/2019 |
| BDTM.58 | Publication of Updated Special Details - High-Mast Lighting | 12/11/2015 | | | | Obsolete, replaced by BDTM.59 |
| BDTM.66 | Update to EDSM I.1.1.28 Procedure for Final Plan Transmittal and Final Plan Modifications | 1/17/2017 | | | | Obsolete, replaced by BDTM.100 |
| BDTM.71 | Bridge Standards Updated for 2016 Specifications | 3/16/2017 | | | | Addressed by BDTM.104, Section 9.3.3. |
| BDTM.81 | Design of Ladders and Access Systems | 6/11/2018 | | | | Revised by BDTM.81.1. |
| BDTM.86 | MASH Implementation - Impact Attenuators | 2/12/2019 | | | | Now the spec and the AML are in agreement and the process outlined in BDTM 86 is no longer needed |