

# Monthly CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
Str. # 61042320104941 Recall # 051450 Route: LA 70  
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: ✓  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of the structure with a transit level. There were no changes when compared to previous inspections.

Inspected By: Brandon Magruder & Billy Balfantz  
Date: 1/26/16

# Grand Bayou

Date 1/26/16

| TBM      |   | 10.0 ft |
|----------|---|---------|
| BS       |   | 6.28    |
| HI       |   |         |
| Bent No. |   | BS      |
| 1        | L | 4.33    |
|          | R | 4.27    |
| 2        | L | 4.31    |
|          | R | 4.28    |
| 3        | L | 4.27    |
|          | R | 4.26    |
| 4        | L | 4.24    |
|          | R | 4.28    |
| 5        | L | 4.28    |
|          | R | 4.29    |
| 6        | L | 4.27    |
|          | R | 4.26    |
| 7        | L | 4.28    |
|          | R | 4.28    |
| 8        | L | 4.29    |
|          | R | 4.29    |
| 9        | L | 4.33    |
|          | R | 4.35    |