

# Monthly CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS  
 Str. # 61042320104941 Recall # 051450 Route: LA 70  
 Bridge Name/Feature Crossed: Grand Bayou

Approaches:	<u>✓</u>	
Roadway:	<u>✓</u>	
Deck:	<u>✓</u>	√ - If element of structure was inspected
Bearings:	<u>N/A</u>	N/A - If element does not apply to structure
Stringers:	<u>N/A</u>	
Girders (Conc./Steel):	<u>N/A</u>	
Piling:	<u>✓</u>	
Caps/Piers:	<u>✓</u>	Were Pictures Taken: YES or <u>NO</u>
Backwalls:	<u>✓</u>	
Wingwalls:	<u>N/A</u>	
Footings:	<u>N/A</u>	
Waterway:	<u>✓</u>	
Embankment (Scour):	<u>✓</u>	
Conc. Spall/Cracks:	<u>✓</u>	

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of the structure with a transit level. There were no changes when compared to previous inspections.

Inspected By: Brandon Magruder + Billy Balfantz  
 Date: 2/18/16

# Grand Bayou

Date 2/18/16

TBM		10.0 ft
BS		6.39
HI		
Bent No.		BS
1	L	4.45
	R	4.39
2	L	4.43
	R	4.40
3	L	4.39
	R	4.38
4	L	4.36
	R	4.39
5	L	4.39
	R	4.39
6	L	4.39
	R	4.38
7	L	4.40
	R	4.40
8	L	4.40
	R	4.41
9	L	4.45
	R	4.48