

Monthly CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS
Str. # 61042320104941 Recall # 051450 Route: LA 70
Bridge Name/Feature Crossed: Grand Bayou

- Approaches:
- Roadway:
- Deck:
- Bearings: N/A
- Stringers: N/A
- Girders (Conc./Steel): N/A
- Piling:
- Caps/Piers:
- Backwalls:
- Wingwalls: N/A
- Footings: N/A
- Waterway:
- Embankment (Scour):
- Conc. Spall/Cracks:

√ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of structure with a transit level. There were no changes when compared to previous inspections.

Inspected By: Brandon Magruder & Billy BALTANTZ
Date: 11/23/15

Grand Bayou

Date 11/23/15

TBM		10.0 ft
BS		6.34
HI		
Bent No.		BS
1	L	4.39
	R	4.31
2	L	4.36
	R	4.34
3	L	4.32
	R	4.32
4	L	4.30
	R	4.33
5	L	4.33
	R	4.31
6	L	4.33
	R	4.32
7	L	4.34
	R	4.34
8	L	4.35
	R	4.35
9	L	4.38
	R	4.41