

Monthly CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS
Str. # 61042320104941 Recall # 051450 Route: LA 70
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓
Roadway: ✓
Deck: ✓
Bearings: N/A
Stringers: N/A
Girders (Conc./Steel): N/A
Piling: ✓
Caps/Piers: ✓
Backwalls: ✓
Wingwalls: N/A
Footings: N/A
Waterway: ✓
Embankment (Scour): ✓
Conc. Spall/Cracks: ✓

√ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or (NO)

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of structure with a Transit level. There were no changes when compared to previous inspection.

Inspected By: Brandon Magruder + Billy Baltantz
Date: 12/21/2015

Grand Bayou

Date 12/21/15

	TBM	10.0 ft
	BS	6.26
	HI	
Bent No.		BS
1	L	4.32
	R	4.25
2	L	4.29
	R	4.26
3	L	4.25
	R	4.24
4	L	4.22
	R	4.26
5	L	4.26
	R	4.24
6	L	4.25
	R	4.24
7	L	4.26
	R	4.26
8	L	4.27
	R	4.27
9	L	4.31
	R	4.34